فاست الرازات

20 1AN

25X1 25X1

Chief, Space, Maintenance & Facilities Branch, Office of Logistics

Deputy Director of Security (PPS), Office of Security

Security Construction - Curic Ball

31.3

REF.: Hemorendum dated 16 October 1957 from C/MRD to C/PhySD, subject: Security Specifications - Wings A, B, and C - Curie Hall

	1. The security storage problems referred to in the attached memorandum have been surveyed by Survey Branch,					
25X1	Physical Security Division, OS; in the company of Chief, Machine Records Division, Office of the Comptroller; and of your office.					
	2. The specific occurity construction items, noted on the attached floor plans by Mr. have been reviewed by CIA Safety Officer, OS. He has advised that the CEA Fire Marshal disapproves of the proposal that a door be installed in the fire wall between the 1200 Wing of Curic Hall and Room 121. He also requests that an emergency exit door equipped with bar and bracket locking mechanism be installed in the left outside wall of the 1200 Wing, insediately to the front of the secure area. (Notations on attached floor plan)					
	3. In addition to the items noted on the stinched floor plans					

security construction items also be included.

a. Install expanded metal on entrance door to 1000 Wing. Secure to door with carriage bolts; peen bolt ends.

and those suggested by _____ it is requested that the following

- b. Install expanded metal window grilles on windows in Rooms 1102, 1104, and 1106.
- c. Install expended metal on door leading from corridor into Room 123; secure metal to door with carriage bolts and peen bolt ends.
- d. In view of the nature of the material contained in these Wings, it is recommended that a rate-of-rise fire detection system be installed. It is noted that in order to

CHATT

Approved For Release 2006/04/13 : CIA-RDP70-00211R000900110002-7

SUBJECT: Security Construction - Curic Hall

attain fire protection for the Wings involved in this request, it is necessary to install the rate-of-rise system in the entire west portion of the building.

be notified upon completion of the above construction. Final survey and arrangements for the installation of MP type combination locks with escape mechanisms on the entrance doors of the respective areas will be made at that time.

25X1

Attachments:

Ref. memo, v/floor plans Memo dtd 20 Dec 57 from CIA Safety Officer

OS:PhySD/SB/ (27 Dec 57)

Distribution:

O&1 - Addressee, w/attach

1 - OS/DD/FPS, w/o attach

1 - 4/Th, 30/08; w/o attach <-

1 - Safo/OS, w/o attach

1 - SB Chrono, w/attach

1 - Reading, w/o attach

ILLEGIB

25X1

ILLEGIB

Approved For Release 2006/04/13 : CIA-RDP7g-00211R000900110002-7

	SINDER WILL CHE	CK CLASSIFICATION	TOP AND	воттом	
	UNCLASSIFIED	CONFIDEN	TIAL	SECRET	
	Q .	RAL INTELLIGENCE A			
	OFFI	CIAL ROUTING	SLIP		
TO NAME AND ADDRESS			INITIAL	S DATE	
1					
2					
3					
4				·	
5					
6					
	ACTION	DIRECT REPLY	PREP	ARE REPLY	
	APPROVAL	DISPATCH	RECOMMENDATION		
	COMMENT	FILE	RETURN		
	CONCURRENCE	INFORMATION	SIGNATURE		
ne ple		plez louver beg	Λίαε	V A	
FOLD HERE TO RETURN TO SENDER					
FROM: NAME, DORESS AND PHONE NO. DATE					
byed For Release Prince 13 : CONTROL TO 11 Rong 1 R					
bye	d FainRakessie DO)6/04/13 · CONJERDE	970LA01021	1Roho®®GR®ãodí	

FORM NO. 237 Replaces Form 30-4 which may be used.